




F16.3


20




F16.2B














F16.5






















FIG. 13












CoH O.D.	90.09	0.09	0.09	0.09	0.09	0.09	0.09	0.086	0.086	0.086	0.083
Cell I.D.	0.06	0.06	0.06	0.06	0.06	0.06	0.06	0.053	0.053	0.054	0.054
Clip Advancing Wire O.D.	0.017	0.017	0.017	0.015	0.02	0.02	0.0%	0.017	0.017	0.017	0.017
Clip Advancing Wire O.D. End Effects Mire O.D. Barner Sheath	0.011	0.011	0.011	0.011	0.011	0.011	0.011	0.009	0.009	0.009	0.009
Barner Sheath	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES	YES
	RUN #1	RUN #2	RUN #3	RUN#4	RUN#5	RUN #6	RUN #7	RUN#8	RUN #9	RUN #10	RUN #11
1 16	0.46	0.24	0.32	0.54	0.59	0.56	0.45	0.87	0.4	0.57	0.77
2 lb	1.19	0.75	0.9	1.07	1.07	1.07	0.69	1.62	1.12	1.02	1
3 //5	1.67	1.24	1.44	1.51	1.9	1.7	1.02	2.07	1.61	1.39	1,77
4 lb	2.19	1.81	1.98	2.62	2.3	2.6	1.51	2.61	2.01	2.09	2.76
5 16	2.74	2.35	2.59	2.05	3 07	2.98	2.26	3.5	2.44	3.19	3.15
8 /b	3.27	2.82	2.61	211	3.68	3.72	2.56	3.87	2.78	3.5	3.61
7 lb	3.32	3.12	3.37		3.93	3.8	3.34	4.56	3.54	3.92	4.48
8 /b	3.82	3.42			4.03	4.08	3,54	4.61	4.28	4.42	5.17
Weight Position	11 lb	11 lb 1 loop	11 lb 2 loops	11 lb	11 lb no loops	11 lb	11 lb Z loops	11 lb	11 lb 2 loops	11 (b	11 lb

F16.22

EFFICIENCY PLOT



F16. Z3